

Download Johnson Evinrude Service Manual 40 Vro

Fuel Pump Rebuild Kit for Johnson Evinrude Outboard. A fuel pump rebuild kit is needed every so often with outboard motors. The inner rubber diaphragm can develop cracks or pin holes that effect proper fuel flow, and inner check valves and springs can break causing complete pump failure. MarineEngine.com does not offer troubleshooting assistance or repair advice by email or by telephone. You are invited to join our public Boat Repair Forum to seek assistance from other members. You may also visit the Boat Motor Manuals section of our site to obtain a service manual. I've researched the archives in regard to OMC VRO systems, and found a lot of info in regard to this topic. But maybe somebody could clear up a few basic questions in regard to a 1986 Montauk with 1986 Evinrude 90-HP. Year of Manufacture : This is important in any repair, for obvious reasons. Prior to 1979, Johnson used the last 2 digits of the year in the model number. As a model 10R78M, would indicate a 10 hp, Rope starter, 1978 year of manufacture and M m odel revision. Since this does not have in the code L between the hp designation and the year, that would mean it is a short shaft version.